

WRITE TERMINATION CONDITIONS  
 WRITE EXTENSION CONDITIONS  
 MEASUREMENT CONDITIONS

FIG. 1




FIG. 2

LOG MEMORY ADDRESS	MEASUREMENT INPUT DATA	MEASUREMENT RESULT DATA	MEASUREMENT EXPECTATION DATA	MEASUREMENT DETERMINATION DATA
0	0	HIGH	HIGH	PASS
1	1	LOW	LOW	PASS
2	2	HIGH	HIGH	PASS
3	3	LOW	LOW	PASS
4	0	HIGH	HIGH	PASS
5	1	LOW	LOW	PASS
6	2	HIGH	HIGH	PASS
7	3	HIGH	LOW	FAIL
n-1	62	HIGH	HIGH	PASS
n	63	LOW	LOW	PASS

FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8

